

COPPER CARBONATE

**Characteristics:**

Copper carbonate is the most common source of copper oxide in glazes. It is used to achieve blue and green in glazes. Above cone 8, copper is very volatile and escapes glazes as a vapor and may influence the color of other glazed pieces. In reduction firing, copper provides copper red.