

# OCHRE

SiO <sub>2</sub>	25.08 %
Al <sub>2</sub> O <sub>3</sub>	6.02
MgO	0.20
Fe <sub>2</sub> O <sub>3</sub>	55.16
CaO	0.50
MnO	3.01
L.O.I.	10.03

**Characteristics:**

Ochre is used as a colorant in glazes.